

State of Vermont

Department of Fish and Wildlife
Department of Forests, Parks and Recreation
Department of Environmental Conservation
State Geologist
RELAY SERVICE FOR THE HEARING IMPAIRED
1-800-253-0191 TDD>Voice
1-800-253-0195 Voice>TDD

AGENCY OF NATURAL RESOURCES
Department of Environmental Conservation
Waste Management Division
103 South Main Street / West Building
Waterbury, Vermont 05671-0404
(802) 241-3888
FAX (802) 241-3296

December 9, 1997

LAWRENCE AND GWEN BOHANNON HENRYS SPORTSMANS COTTAGES RD #1 BOX 177 SOUTH ALBURG VT 05440

RE: Site Management Activity Completed (SMAC), Henry's Sportsmans' Cottages, South Alburg, Vermont (Site #93-1480)

Dear Mr. and Mrs. Bohannon:

The Sites Management Section (SMS) has received the letter from you dated November 12, 1997 regarding the 12 yards of petroleum contaminated soil. The SMS has also reviewed information previously submitted by Lincoln Applied Geology concerning this site.

With this information, the SMS can now make the following conclusions:

- On October 5, 1993, a 1,000 gallon gasoline UST was removed from Henry's Sportsmans'
 Cottages site.
- During the UST removal, soils surrounding the USTs were found to be contaminated with
 petroleum compounds at concentrations above SMS guideline levels, as measured with a
 photionization device (PID). Twelve yards of petroleum contaminated soil were removed
 from the ground for on-site treatment by polyencapsulation.
- One groundwater monitoring well was installed in the UST excavation area to determine the impact on groundwater. Groundwater samples collected from these wells on February 3, 1994 showed that petroleum had affected the groundwater quality at this site at concentrations above the Vermont Groundwater Enforcement Standards. Continued monitoring of the groundwater showed decreasing concentrations in sampling conducted in May of 1994, and no detectable concentrations in samples collected in October of 1994.
- The stockpiled soils were properly treated by polyencapsulation, and have been spread on site.
- PID screening of the residence adjacent to the underground storage tank area, and inspection of the Lake Champlain shoreline provided no evidence of petroleum contamination. The on

site water supply well is located 500 feet from the UST area, and was not determined to be at risk from this contamination.

• No unacceptable risk to human health and the environment is present due to any residual contamination remaining in the ground from the removed gasoline UST.

Based on the above, the SMS is assigning this site a Site Management Activity Completed (SMAC) designation. This SMAC designation does not release you of any past or future liability associated with the petroleum contamination onsite. It does, however, mean that the SMS is not requesting any additional work in response to the 1993 UST removal.

Please feel free to call with any questions.

Sincerely,

George Desch, Chief, P.E. Sites Management Section

CC: Alburg Selectboard DEC Regional Office

CBS/petro/Henrysmac.wpd